

**USEPA – Region 6, Dallas, Texas**  
**Superfund Site Inspection Report**  
**Hurricane Ike Follow-up**

**\*Site:** State Marine of Port Arthur

**\*Location:** Highway 87, 4.5 miles NE Port Arthur, Jefferson County, Texas

**\*Date:** 09/19/08

**\*Remedial Action (RA):** Complete - remove hazardous liquids and soil – dispose offsite.

**\*Site Status:** Institutional Controls.

**\*Contacts:** None.

**\*Site Conditions:** Good. Construction completion.

**\*Recommendation:** no action required.

**\*Comments:** Hurricane winds from South. Storm Surge grasses onsite.

**\*Pictures:** **Photo#1:** North boundary of site shot South. Note yellow Monitoring well posts.

**\*Name:** Charles David Abshire **\*Signature:** \_\_\_\_\_